Chemwatch Independent Material Safety Data Sheet Issue Date: 29-Jan-2007

NC317TCP

CHEMWATCH 5074-01 Version No:2.0 CD 2009/2 Page 1 of 9

Section 1 - CHEMICAL PRODUCT AND COMPANY IDENTIFICATION

PRODUCT NAME

KEMBLA LARGE DIAM KEMLAG

SYNONYMS

"Kem Lag green low density LDPE Polyethylene pellets extrusion", "pipe insulation moulding"

PRODUCT USE

Blow extrusion moulding of molten polymer mix to form a continuous insulation covering on large diameter copper water pipe.

SUPPLIER

Company: Metal Manufactures

Address:

Gloucester Boulevarde

Port Kembla NSW, 2505 AUS

Telephone: +61 2 4223 5300

Fax: +61 2 4223 5288

Email: hzotter@kembla.com.au

Section 2 - HAZARDS IDENTIFICATION

STATEMENT OF HAZARDOUS NATURE

NON-HAZARDOUS SUBSTANCE. NON-DANGEROUS GOODS. According to the Criteria of NOHSC, and the ADG Code.

CHEMWATCH HAZARD RATINGS



POISONS SCHEDULE

None

RISK

» Limited evidence of a carcinogenic effect*.

* (limited evidence).

SAFETY

- » Do not breathe dust.
- » Avoid contact with skin.

Section 3 - COMPOSITION / INFORMATION ON INGREDIENTS

NAME
Cosmothene F117- 1 low density polyethylene as polyethylene
APS Culamix Green G5191LTU

CAS RN
9002-88-4
96
4

continued...

Chemwatch Independent Material Safety Data Sheet Issue Date: 29-Jan-2007

Issue Date: 29-Jan-2007 NC317TCP CHEMWATCH 5074-01 Version No:2.0 CD 2009/2 Page 2 of 9

Section 3 - COMPOSITION / INFORMATION ON INGREDIENTS

Section 4 - FIRST AID MEASURES

SWALLOWED

• For advice, contact a Poisons Information Centre or a doctor.

EYE

- » If this product comes in contact with the eyes:
- Immediately hold eyelids apart and flush the eye continuously with running water.
- Ensure complete irrigation of the eye by keeping eyelids apart and away from eye and moving the eyelids by occasionally lifting the upper and lower lids.
- Continue flushing until advised to stop by the Poisons Information Centre or a doctor, or for at least 15 minutes.
- Transport to hospital or doctor without delay.
- Removal of contact lenses after an eye injury should only be undertaken by skilled personnel.

SKIN

- » In case of burns:
- Immediately apply cold water to burn either by immersion or wrapping with saturated clean cloth.
- DO NOT remove or cut away clothing over burnt areas. DO NOT pull away clothing which has adhered to the skin as this can cause further injury.
- DO NOT break blister or remove solidified material.
- Quickly cover wound with dressing or clean cloth to help prevent infection and to ease pain.
- For large burns, sheets, towels or pillow slips are ideal; leave holes for eyes, nose and mouth.
- DO NOT apply ointments, oils, butter, etc. to a burn under any circumstances.
- Water may be given in small quantities if the person is conscious.
- Alcohol is not to be given under any circumstances.
- Reassure.
- Treat for shock by keeping the person warm and in a lying position.
- Seek medical aid and advise medical personnel in advance of the cause and extent of the injury and the estimated time of arrival of the patient.

INHALED

- If dust is inhaled, remove from contaminated area.
- Encourage patient to blow nose to ensure clear passage of breathing.
- If irritation or discomfort persists seek medical attention.
- or If fumes or combustion products are inhaled remove from contaminated area.
- Lay patient down. Keep warm and rested.
- Prostheses such as false teeth, which may block airway, should be removed, where possible, prior to initiating first aid procedures.
- Apply artificial respiration if not breathing, preferably with a demand valve resuscitator, bag-valve mask device, or pocket mask as trained. Perform CPR if necessary.
- Transport to hospital, or doctor.

NOTES TO PHYSICIAN

» Treat symptomatically.

Section 5 - FIRE FIGHTING MEASURES

EXTINGUISHING MEDIA

- Foam.
- Dry chemical powder.
- BCF (where regulations permit).
- Carbon dioxide.
- Water spray or fog Large fires only.

Chemwatch Independent Material Safety Data Sheet Issue Date: 29-Jan-2007

NC317TCP

CHEMWATCH 5074-01 Version No:2.0 CD 2009/2 Page 3 of 9 Section 5 - FIRE FIGHTING MEASURES

FIRE FIGHTING

- Alert Fire Brigade and tell them location and nature of hazard.
- Wear breathing apparatus plus protective gloves for fire only.
- Prevent, by any means available, spillage from entering drains or water courses.
- Use fire fighting procedures suitable for surrounding area.
- DO NOT approach containers suspected to be hot.
- Cool fire exposed containers with water spray from a protected location.
- If safe to do so, remove containers from path of fire.
- Equipment should be thoroughly decontaminated after use.

FIRE/EXPLOSION HAZARD

- » Combustible. Will burn if ignited Combustible
- Slight fire hazard when exposed to heat or flame.
- Heating may cause expansion or decomposition leading to violent rupture of containers.
- On combustion, may emit toxic fumes of carbon monoxide (CO).
- May emit acrid smoke.
- Mists containing combustible materials may be explosive.

NOTE: Burns with intense heat. Produces melting, flowing, burning liquid and dense acrid black smoke. Decomposes on heating and produces acrid and toxic fumes of: carbon monoxide (CO), and minor amounts of formaldehyde, acrolein.

FIRE INCOMPATIBILITY

» Avoid contamination with strong oxidising agents as ignition may result.

Avoid creating dust - may present dust explosion hazard. Dry dust can be electrostatically charged by turbulence, pneumatic transport, pouring, in exhaust ducts and during transport. Build-up of electrostatic charge may be prevented by grounding.

HAZCHEM: None

PERSONAL PROTECTION

Glasses:

Chemical goggles.

Gloves:

PVC chemical resistant type.

Leather Gloves. Respirator:

Particulate

Section 6 - ACCIDENTAL RELEASE MEASURES

MINOR SPILLS

- » Slippery when spilt.
- Clean up all spills immediately.
- Avoid contact with skin and eyes.
- Wear protective clothing, gloves, safety glasses and dust respirator.
- Use dry clean up procedures and avoid generating dust.
- Sweep up or
- Vacuum up (consider explosion-proof machines designed to be grounded during storage and use).
- Place in clean drum then flush area with water.

MAJOR SPILLS

- » Slippery when spilt.
- Clean up all spills immediately.
- · Avoid contact with skin and eyes.
- Wear protective clothing, gloves, safety glasses and dust respirator.
- Use dry clean up procedures and avoid generating dust.

Chemwatch Independent Material Safety Data Sheet Issue Date: 29-Jan-2007

NC317TCP

CHEMWATCH 5074-01 Version No:2.0 CD 2009/2 Page 4 of 9

Section 6 - ACCIDENTAL RELEASE MEASURES

- Sweep up or
- Vacuum up (consider explosion-proof machines designed to be grounded during storage and use).
- Place in clean drum then flush area with water.

Personal Protective Equipment advice is contained in Section 8 of the MSDS.

Section 7 - HANDLING AND STORAGE

PROCEDURE FOR HANDLING

- Avoid generation of static electricity. Earth all lines and equipment.
- Avoid smoking, naked lights or ignition sources.
- Limit all unnecessary personal contact.
- Wear protective clothing when risk of exposure occurs.
- Use in a well-ventilated area.
- When handling DO NOT eat, drink or smoke.
- Always wash hands with soap and water after handling.
- Avoid physical damage to containers.
- Use good occupational work practice.
- Observe manufacturer's storing and handling recommendations.

SUITABLE CONTAINER

» Multi-ply paper bag with sealed plastic liner or heavy gauge plastic bag.

NOTE: Bags should be stacked, blocked, interlocked, and limited in height so that they are stable and secure against sliding or collapse. Check that all containers are clearly labelled and free from leaks. Packing as recommended by manufacturer.

STORAGE INCOMPATIBILITY

» Avoid storage with oxidisers.

Avoid contamination of water, foodstuffs, feed or seed.

STORAGE REQUIREMENTS

- Keep dry.
- Store in original containers.
- · Keep containers securely sealed.
- No smoking, naked lights or ignition sources.
- Store in a cool, dry, well-ventilated area.
- Store away from incompatible materials and foodstuff containers.
- Protect containers against physical damage and check regularly for leaks.
- Observe manufacturer's storing and handling recommendations.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS















+: May be stored together

O: May be stored together with specific preventions

X: Must not be stored together

Chemwatch Independent Material Safety Data Sheet Issue Date: 29-Jan-2007

NC317TCP

CHEMWATCH 5074-01 Version No:2.0 CD 2009/2 Page 5 of 9

Section 8 - EXPOSURE CONTROLS / PERSONAL PROTECTION

EXPOSURE CONTROLS

The following materials had no OELs on our records

polyethylene:

CAS:9002-88-4

MATERIAL DATA

» None assigned. Refer to individual constituents.

INGREDIENT DATA

POLYETHYLENE:

PERSONAL PROTECTION







EYE

- Safety glasses with side shields; or as required,
- Chemical goggles.
- Contact lenses may pose a special hazard; soft contact lenses may absorb and concentrate irritants. A written policy document, describing the wearing of lens or restrictions on use, should be created for each workplace or task. This should include a review of lens absorption and adsorption for the class of chemicals in use and an account of injury experience. Medical and first-aid personnel should be trained in their removal and suitable equipment should be readily available. In the event of chemical exposure, begin eye irrigation immediately and remove contact lens as soon as practicable. Lens should be removed at the first signs of eye redness or irritation - lens should be removed in a clean environment only after workers have washed hands thoroughly. [CDC NIOSH Current Intelligence Bulletin 59].

HANDS/FEET

- » Wear chemical protective gloves. eg. PVC gloves with barrier cream Wear safety footwear. When handling hot material, wear • Protective gloves eg. Leather gloves or gloves with Leather facing.
- When handling hot materials wear heat resistant, elbow length gloves.
- Rubber gloves are not recommended when handling hot objects, materials.

OTHER

- Overalls.
- Eyewash unit.

Ensure ready access to a burns first aid kit.

RESPIRATOR

100+ x ES

Protection Factor Half- Face Respirator Full- Face Respirator Powered Air Respirator 10 x ES P1 Air- line* PAPR-P1-_ _ PAPR- P2 50 x ES Air-line** P2 100 x ES P3 Air- line* PAPR-P3

Air- line**

* - Negative pressure demand ** - Continuous flow.

The local concentration of material, quantity and conditions of use determine the type of personal protective

Chemwatch Independent Material Safety Data Sheet

Issue Date: 29-Jan-2007

NC317TCP

CHEMWATCH 5074-01 Version No:2.0 CD 2009/2 Page 6 of 9

Section 8 - EXPOSURE CONTROLS / PERSONAL PROTECTION

equipment required. For further information consult site specific CHEMWATCH data (if available), or your Occupational Health and Safety Advisor.

ENGINEERING CONTROLS

» KEEP dry. High temperature processing of material which has become damp may cause violent steam explosion in unvented machinery.

Area where polymer is heat processed should be ventilated to remove vapour, fumes released during all stages of processing Use in a well-ventilated area.

General exhaust is adequate under normal operating conditions. Local exhaust ventilation may be required in specific circumstances. If risk of overexposure exists, wear approved respirator. Correct fit is essential to obtain adequate protection. Provide adequate ventilation in warehouse or closed storage areas. Air contaminants generated in the workplace possess varying "escape" velocities which, in turn, determine the "capture velocities" of fresh circulating air required to effectively remove the contaminant.

Type of Contaminant: solvent, vapours, degreasing etc., evaporating from tank (in still air). aerosols, fumes from pouring operations, intermittent container filling, low speed conveyer transfers, welding, spray drift, plating acid fumes, pickling (released at low velocity into zone of active generation) direct spray, spray painting in shallow booths, drum filling, conveyer loading, crusher dusts, gas discharge (active generation into zone of rapid air motion) grinding, abrasive blasting, tumbling, high speed wheel generated dusts (released at high initial velocity into zone of very high rapid

Air Speed: 0.25- 0.5 m/s (50- 100 f/min)

0.5- 1 m/s (100- 200 f/min.)

1- 2.5 m/s (200- 500 f/min.)

2.5- 10 m/s (500- 2000 f/min.)

Within each range the appropriate value depends on:

Lower end of the range

air motion).

1: Room air currents minimal or favourable to capture

2: Contaminants of low toxicity or of nuisance value only.

3: Intermittent, low production.

4: Large hood or large air mass in motion

Upper end of the range

1: Disturbing room air currents

2: Contaminants of high toxicity

3: High production, heavy use

4: Small hood- local control only

Simple theory shows that air velocity falls rapidly with distance away from the opening of a simple extraction pipe. Velocity generally decreases with the square of distance from the extraction point (in simple cases). Therefore the air speed at the extraction point should be adjusted, accordingly, after reference to distance from the contaminating source. The air velocity at the extraction fan, for example, should be a minimum of 1-2 m/s (200-400 f/min) for extraction of solvents generated in a tank 2 meters distant from the extraction point. Other mechanical considerations, producing performance deficits within the extraction apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when extraction systems are installed or used.

Chemwatch Independent Material Safety Data Sheet Issue Date: 29-Jan-2007

NC317TCP

CHEMWATCH 5074-01 Version No:2.0 CD 2009/2 Page 7 of 9

Section 9 - PHYSICAL AND CHEMICAL PROPERTIES

APPEARANCE

Green coloured mixed granules. Insoluble in water.

Mix of non-food grade polymer and polymer colour masterbatch containing performance enhancing additives.

PHYSICAL PROPERTIES

Solid.

Does not mix with water.

Floats on water.

Molecular Weight: Not available
Melting Range (°C): 106- 112
Solubility in water (g/L): Immiscible
pH (1% solution): Not applicable
Volatile Component (%vol): Nil @ 38 C.
Relative Vapour Density (air=1): > 2
Lower Explosive Limit (%): Not applicable
Autoignition Temp (°C): 380- 400

State: Divided solid

Boiling Range (°C): Not applicable

Specific Gravity (water=1): 0.91- 0.93 melt pH (as supplied): Not applicable

Vapour Pressure (kPa): Negligible Evaporation Rate: Non Volatile Flash Point (°C): 260 approx

Upper Explosive Limit (%): Not applicable Decomposition Temp (°C): 300 approx

Section 10 - CHEMICAL STABILITY AND REACTIVITY INFORMATION

CONDITIONS CONTRIBUTING TO INSTABILITY

- Presence of incompatible materials.
- Product is considered stable.
- Hazardous polymerisation will not occur.

For incompatible materials - refer to Section 7 - Handling and Storage.

Section 11 - TOXICOLOGICAL INFORMATION

POTENTIAL HEALTH EFFECTS

ACUTE HEALTH EFFECTS

SWALLOWED

» Considered an unlikely route of entry in commercial/industrial environments.

Considered to be non toxic but The material may be harmful if swallowed in quantity and may cause physical obstruction of breathing.

Ingestion may result in nausea, abdominal irritation, pain and vomiting.

EYE

» The material is moderately discomforting and may be abrasive to the eyes.

The vapour from heated material is discomforting to the eyes.

SKIN

» The material may be mildly discomforting to the skin.

Molten material is capable of causing severe thermal burns.

INHALED

» Not normally a hazard due to non-volatile nature of product.

Generated dust may be discomforting if inhaled.

Inhalation hazard is increased at higher temperatures.

Chemwatch Independent Material Safety Data Sheet Issue Date: 29-Jan-2007

NC317TCP

CHEMWATCH 5074-01 Version No:2.0 CD 2009/2 Page 8 of 9 Section 11 - TOXICOLOGICAL INFORMATION

The vapour from heated material is discomforting if inhaled.

Inhalation of vapour may result in nausea, headache.

Processing for an overly long time or processing at overly high temperatures may cause generation and release of highly irritating vapours, which irritate eyes, nose, throat, causing red itching eyes, coughing, sore throat.

CHRONIC HEALTH EFFECTS

» Principal routes of exposure are usually by skin contact with the molten material and inhalation of fumes from the heated material.

As with any chemical product, contact with unprotected bare skin; inhalation of vapour, mist or dust in work place atmosphere; or ingestion in any form, should be avoided by observing good occupational work practice.

TOXICITY AND IRRITATION

» Not available. Refer to individual constituents.

POLYETHYLENE:

» unless otherwise specified data extracted from RTECS - Register of Toxic Effects of Chemical Substances.

TOXICITY IRRITATION

Oral (rat) LD50: > 3000 mg/kg

» The substance is classified by IARC as Group 3:

NOT classifiable as to its carcinogenicity to humans.

Evidence of carcinogenicity may be inadequate or limited in animal testing.

polyethylene pyrolyzate

Inhalation (mouse) LC50: 12000 mg/m³/30m

CARCINOGEN

polyethylene International Agency Group 3

for Research on Cancer (IARC) Carcinogens

Section 12 - ECOLOGICAL INFORMATION

No data

Ecotoxicity

Ingredient Persistence: Persistence: Air Bioaccumulation Mobility

Water/Soil

Kembla Large Diam No data

Kemlag

polyethylene LOW No data LOW HIGH

Section 13 - DISPOSAL CONSIDERATIONS

- Consult manufacturer for recycling options and recycle where possible .
- Consult State Land Waste Management Authority for disposal.
- Incinerate residue at an approved site.
- Recycle containers if possible, or dispose of in an authorised landfill.

Chemwatch Independent Material Safety Data Sheet Issue Date: 29-Jan-2007

NC317TCP

CHEMWATCH 5074-01 Version No:2.0 CD 2009/2 Page 9 of 9

Section 14 - TRANSPORTATION INFORMATION

HAZCHEM: None (ADG6)

NOT REGULATED FOR TRANSPORT OF DANGEROUS GOODS: UN, IATA, IMDG

Section 15 - REGULATORY INFORMATION

POISONS SCHEDULE: None

REGULATIONS

Kembla Large Diam Kemlag (CAS: None): No regulations applicable

Regulations for ingredients polyethylene (CAS: 9002-88-4) is found on the following regulatory lists; Australia Inventory of Chemical Substances (AICS) International Agency for Research on Cancer (IARC) Carcinogens

Section 16 - OTHER INFORMATION

» Classification of the preparation and its individual components has drawn on official and authoritative sources as well as independent review by the Chemwatch Classification committee using available literature references.

A list of reference resources used to assist the committee may be found at: www.chemwatch.net/references.

» The (M)SDS is a Hazard Communication tool and should be used to assist in the Risk Assessment. Many factors determine whether the reported Hazards are Risks in the workplace or other settings. Risks may be determined by reference to Exposures Scenarios. Scale of use, frequency of use and current or available engineering controls must be considered.

This document is copyright. Apart from any fair dealing for the purposes of private study, research, review or criticism, as permitted under the Copyright Act, no part may be reproduced by any process without written permission from CHEMWATCH. TEL (+61 3) 9572 4700.

Issue Date: 29-Jan-2007 Print Date: 9-Nov-2009

This is the end of the MSDS.